

A Reconnaissance Investigation was conducted on April 7, 2022 (Investigation No. 1811241). The investigation was conducted concurrently with the wastewater CCI for the systems associated wastewater treatment plant. A violation was alleged for failure to provide an Air Gap or backflow prevention assembly required by 30 Texas Administrative Code (TAC), Chapter 290.47(f) at the meter for a residence or establishment where an actual or potential contamination hazard exists (Violation No. 812509). Specifically, there was no backflow protection at two of the systems lift stations where a hose spigot is located onsite.